Whittier Tunnel Surface Improvements

Portage Glacier Road Whittier, AK|*** 99510




Date Sun 03/14/2021


Job # 119776

Prepared By Gabriel Thomas









Weather

3:00 AM

5° 人

Clear

Wind: 4 MPH | Precipitation: .0" | Humidity: 71%

6:00 AM

)° 👍

Mostly Cloudy

Wind: 2 MPH | Precipitation: .0" | Humidity: 83%

10:00 PM

22°



Snov

Wind: 3 MPH | Precipitation: .11" | Humidity: 94%

Work Logs					
Name	Description	Quantity	Total Hours	Total Hours To Date	
ARRC Crew	Ian Pierce - flagger - form B - r3434 Gabriel Thomas - PM - R3612 R3434 needs an oil change. Suggest take to anchorage in the AM and return in evening. Would like to do this when fuel tank is low to maximize fuel prices in anchorage. Gabriel Thomas 03/15/21 12:02AM	2	17	17	
Granite Crew	Ripped asphalt on north rail (on safe house side of track) starting in front of, and north of safe house 8 and replaced with rubber flange filler. SH 8, two / three passes with loader bucket teeth mounts. 38% of eclipse are broken on first 5 panels, less are broken track north of SH8 13 panels of production. Starting 2 panels north of phone 582 Slight damage to concrete in tubs. Need to keep an eye	8	68	171.5	

	on it.			
	Rubber installation is smooth, no D clips, D clips will present a challenge for installation			
	Asphalt removal is damaging the joint seals, joint seals appear to be in bad shape to start with.			
	Granite has excavator on order			
	Gabriel Thomas 03/15/21 12:22AM			
Whittier Tunnel Inspection and Daily Reporting		0	0	0
Total		10	85	188.5

Time Cards	No entry
• • • • • • • • • • • • • • • •	

Materials				
Material	Cost Code	Day Total	Week Total	Quantities to Date
Polycorp Field Rubber Flangeway One side of track		97.5 If	247.5	247.5 If
Gabriel Thomas 03/15/21 03:53PM				
Polycorp Gauge Rubber Flangeway		97.5 If	247.5 If	247.5 If
One side of track Gabriel Thomas 03/15/21 03:53PM				

Equipment				
Equipment	Supplier/Sub	Hours In Use	Notes	Total Days On Site
Air Compressor - Sullair A765-05 Granite		0		1

General Notes

- 1. 2140 SB Whittier freight confirmed south of tunnel portal Gabriel Thomas | 03/14/21 | 09:47PM
- 2. Switch freezing causing delay Friday Gabriel Thomas | 03/14/21 | 11:20PM





- **3.** Need to get Dispatch to notify Arrc flagger when train is totally south of girdwood detector. Train is about 40 min travel from this detector to the Whittier tunnel.
- **4.** In the past the portage tunnel was left open over night by section to prevent Tom from having to man the portage doors. Confirm that flagger can man doors while on form B
- **5.** Need to confirm weekend hours with tunnel control and granite Gabriel Thomas 103/15/21 104:55AM

Site Safety Observations

No entry


Quality Control Observations

No entry

Survey				
Questions	N/A No Yes Description			
1. Any accidents on site today?	Safety meeting held at 10:30 PM Gabriel Thomas 03/15/21 12:43AM			
2. Any schedule delays occur?	No trains Gabriel Thomas 03/15/21 12:43AM			
3. Did weather cause any delays?	Stormy in Whittier Gabriel Thomas 03/15/21 12:43AM			
4. Any visitors on site?	No Gabriel Thomas 03/15/21 12:43AM			
5. Any areas that can't be worked on?				
6. Any equipment rented on site?				

Attachments





I, Gabriel Thomas, have reviewed and completed this report.

Gabriel Thomas | 03/15/21 | 06:24AM