

Alaska Railroad Corporation 327 W. Ship Creek Ave. Anchorage, AK 99501

March 11, 2022

Addendum 1 ITB # 22-15-209641 Anchorage Shop Earthquake Repairs

Addendum number 1 has been issued for questions and clarifications.

The Closing Date for this ITB <u>has not changed</u>.

Bids will be received until Thursday <u>March 17, 2022</u> @ 3:00 PM Alaska time.

Questions:

- Has the completion date for building 30 concrete and grout replacement changed?
 Yes, the date has been extended allowing the work to be performed between October 1 and December 31, 2022.
- 2) Would the ARRC consider allowing for concurrent performance period of the structural steel repairs with the same completion date?
 - Yes completion of the structural steel will date will be extended to December 31, 2022. This will allow for earlier completion or concurrent work and completion with building 30.
- 3.) Can you verify what size drawings the scale is for (1/4" = 1') on detail A/S2 of the Building 26 select cross brace replacement drawings?

Yes, the scale is correct when printed on full scale on 11 x 17 paper. All work for all three shops is less than 33 feet above floor.

Clarifications:

Please replace the following documents in their entirety with the ones attached herein.

Appendix H – Cost Schedule

2022 Anchorage Diesel Shop Building 26 Select Cross Brace Replacement (Revision)

Summary of changes: Sheet S1: Note L.

Sheet S2: Plate D and Clips E quantities

Sheet S3: Detail H, Clips E

Sheet S4: Quantity Double Angle N Sheet S7: Quantity Double Angle NN

Anchorage Car Shop Brace Angle Replacement: Wheel Shop X Brace Angle Replacement (Revision)

Summary of changes:

Sheet G1: Corrected total sheet count

Sheet S1: Removed extraneous dimension from East Wall

Interior Elevation.

Sheet S2: Corrected individual sheet count

Anchorage Building 30 Wheel Truing Shop Track 2 Rail Support Repair

No revisions

All other terms and conditions remain unchanged. If there are any questions regarding this addendum please let me know.

Thank you,

Greg C Goemer

Sr. Contract Administrator Alaska Railroad Corporation

APPENDIX H COST SCHEDULE

<u>COST SCHEDULE</u>: A Bidder's Failure to provide the information requested in this Appendix may be cause for rejection of the bid on the basis on non-responsiveness. Cost shall be bid in accordance to all specifications and drawings incorporated herein.

<u>AWARD CRITERIA</u>: A contract award resulting from this solicitation may be made to the low, responsive, responsible bidder who meets the requirements as set forth in the plans and specifications and compliance thereof. An award may be made in the aggregate of the Base Bid and or any combination of Base Bid and Add Alternates, whichever is deemed by the Contract Administrator to be in the best interest of the ARRC. The successful bidder shall hold unit prices of all additives firm for a period of thirty (30) days from the date of bid opening. Award is contingent on the availability of FTA and ARRC funds.

<u>Description</u>			<u>Cost</u>				
1.	Anchorage Shops Repairs Bldg 26	\$	Lump Sum				
2.	Anchorage Shops Repairs Bldg 28	\$	Lump Sum				
3.	Anchorage Shops Repairs Bldg 30	\$	Lump Sum				
3A	. ADDITIVE ALTERNATE: Bldg 30 Additional Repairs Per plans.	\$	Lump Sum				
laws of he/she	COLLUSION AFFIDAVIT: The United States, that neither he is a member, has, either directly ellusion, or otherwise taken any active Bid.	e/she nor the firm, association or indirectly, entered into any	n, or corporation of which agreement, participated in				
	ndersigned has read the foregoin n by affixing his/her signature belo		to the conditions stated				
BIDDE	ERS NAME AND ADDRESS						
COMP	PANY NAME	SIGNATURE BY AND FO	OR THE BIDDER				
COMP	PANY MAILING ADDRESS	MAILING ADDRESS PRINTED NAME OF ABOVE BIDDER					
CITY,	STATE ZIP CODE	DATE OF BID					
CONT	ACT PHONE NUMBER	CONTACT E-MAIL ADDI	RESS				

SCHEDULE OF VALUES

Item No.	Item Description	Unit	Quantity	Amount Bid
1	Bldg 26: Cross bracing repairs and ladder replacement	Lump Sum	1	
2	Bldg 28: Cross bracing repair and ladder demolition.	Lump Sum	1	
3	Bldg 30: Replace rail grout pads under embedded rail.	Lump Sum	1	

Item No.	Item Description	Unit	Quantity	Amount Bid
A1	Bldg 30 Additional Repairs per drawings.	Lump Sum	1	

Notes:

1 Award of Additive Alternate Bid items is dependent on Owner finances. The successful bidder will be notified of the Owner's intent to award additional work prior to receiving a Contract or Notice to Proceed (NTP).